


Blank 1.5 x 3.25  
 Finished 1.5" diam.  
 Hat 1" to 1 1/8", head 5/8, body 3/4  
 Leave at 3/4" waste on chuck side  
 Burn hat band or use felt tip pin on lathe  
 Drill Screw eye hole while on lathe



Blank 1.75" sq x 4 1/2"  
 Leave at least 3/4" waste for chuck and parting off so finished ornament should be about 3 3/4". Borrow story stick if needed.